

Candle

of the month

Gildewerk
www.gildewerk.com

X-mas tree

YOU WILL NEED:

DMJ-0004G Melting urn or
DMB-00001 Mini bain 1000

DGW-00005 Mould mix or
WAX-00110 Plusmix

KLP-24376 Colour purple or
KLP-06376 or any other colour

KPT-03 x10 Flat wick 3 x 10 (100 m.)
or
KPT-00710 (5 m.)

Mal-00131 Cone mould

Mal-00401 Silicon plug

Mal-00300 Centring needle

Whisk, beaker (1 l.) and fork



- Heat up the wax to 90°C and make a cone shaped candle following the instructions on (www.gildewerk.com > service center > producttips)
- Fill the beaker with about ½ a litre of coloured wax (about ½ colour tablet).
- Beat up the wax, using the whisk, while it is cooling down until it becomes foam. Over dip the candle with the wax foam and tap with the fork softly on the foam to make it piked.
- If the foam gets to cold and solid, just add a little bit of warm wax and beat it up again.

There are a lot creative applications for wax foam, with or without colour.

Use your imagination!

If you're curious about making other candles, please sign up to one of our workshops